




Rocky Mountain
Remediation Services, L.L.C.
... protecting the environment

Rocky Flats Environmental Technology Site
P.O. Box 464
Golden, Colorado 80402-0464
Phone: (303) 966-7000



99-RF-0062

CORRES. CONTROL

LTR. NO.

Originator Ltr Log #

WJM-001-99

99 - RF -0062

January 7, 1999

DIST.	LTR	ENC
CARMEAN, C. H.		
CRAWFORD, A. C.		
FINDLEY, M. E.		
GUINN, L. A.		
HUGHES, F. P.		
LAW, J. E.		
OVERLID, T. W.		
PATTERSON, J. W.		
TRICE, K. D.		
WHEELER, M.		
WOLF, K. A.		

J. J. Lucerna
Kaiser-Hill Company, L.L.C.
Engineering Oversight
Building 115

REVIEW AND UPDATE OF SUYAMA LETTER REGARDING THE DEACTIVATION OF
SUBSTATION 515/516 — WJM-001-99

Ref: R. M. Suyama ltr to J. R. Cable, RMS-051-98, Impacts to Safe Sites of Colorado
Facilities of the Planned Deactivation of Substations 515/516, July 16, 1998

PURPOSE

The purpose of this letter is to review the impacts to the Authorization Basis of Buildings
771/774 and 776/777 that were recently transferred to RMRS. RMRS has determined that the
impacts remain the same as per the above referenced letter.

DISCUSSION

- Building 771/774 impacts include their Basis for Operation and Site Environmental Reports.
Operating and surveillance procedures will require changes to reflect the new configuration.
A planned Out of Tolerance will need to be arranged and transmitted to the Department of
Energy. The building estimates that approximately 320 man-hours will be required for the
above document changes and 88 man-hours for building support. The present facility
budget does not include this activity.
- Building 776/777 would be affected by the actual outage as some building transformers and
2400-volt sources are connected to the feeders that will experience outages for the
deactivation evolution. An extensive outage would adversely impact the facility since an
Emergency Generator source is not available to power some cooling systems and air
compressors. This is a temperature-related issue. During a period of high outside
temperature an outage of four to eight hours would have adverse impacts. During a period
of cool or cold weather an adverse impact may not be experienced for a two to five day
period. Also, some minor changes to the draft Basis for Interim Operation and Stationary
Operating Engineer User Aids will be required. The building can support a limited outage
from the building baseline. There is no impact to the Building 776/777 Authorization Basis
as a result of this work.

CORR. CONTROL	X	X
ADMIN. RECORDS	X	X
RMRS RECORDS	X	X
CONTROL		
TRAFFIC		
PATS/T130G		

CLASSIFICATION:

UCNI		
UNCLASSIFIED	X	X
CONFIDENTIAL		
SECRET		

AUTHORIZED CLASSIFIER

SIGNATURE:

Date:

IN REPLY TO RF CC NO.:

ACTION ITEM STATUS:

☐ PARTIAL/OPEN

☐ CLOSED

LTR APPROVALS:

ORIG. & TYPIST INITIALS:

CPC:hed

RF-46469 (Rev. 9/98)

ADMIN RECORD

IA -A-00133

J. J. Lucerna
January 7, 1999
WJM-001-99
Page 2

RESPONSE REQUIREMENTS

No response is required. If you have any questions, please contact me at extension 5454 or Carl Caimi at extension 4784 or digital pager 212-4174.



W. J. McAndrew, Director
RMRS Engineering

CPC:hed

cc:

C. P. Caimi
G. C. Kellund
M. J. Kobi